



## Replacement Sheet




FIG. 1

Replacement Sheet





FIG. 2

Replacement Sheet

FIG. 3



Replacement Sheet







FIG. 4

## Replacement Sheet



Replacement Sheet

BEST AVAILABLE COPY




FIG. 6

# Replacement Sheet




FIG. 7

BEST AVAILABLE COPY

Replacement Sheet

The diagram illustrates a control panel interface for a 'Replacement Sheet'. The panel includes a large central display (802) and a 'SHAFT ID' input field (800). To the right of the display are three stacked buttons (808) and an 'IGMS' label with a corresponding input field. Below the display is a 'SHAFT MAX' label (804) and a small circular button. The main data area (806) contains a table with 6 rows and 11 columns. The first 5 rows represent individual shaft measurements, and the 6th row is an average ('AVG'). To the right of the table is a column of checkboxes (810). Below the table is a row of five circular buttons (816) and a row of five square buttons (812). The bottom of the panel features a name input field containing 'John Smith' and a row of five circular buttons (816).

|     |      |      |      |     |                          |     |   |     |     |     |
|-----|------|------|------|-----|--------------------------|-----|---|-----|-----|-----|
| 1   | 44.8 | 1.92 | 1.71 | 5.2 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |
| 2   | 43.4 | 1.86 | 1.68 | 4.9 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |
| 3   | 43.6 | 1.83 | 1.51 | 4.8 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |
| 4   | 42.0 | 1.90 | 1.51 | 5.1 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |
| 5   | 46.8 | 2.17 | 1.94 | 6.2 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |
| AVG | 44.1 | 1.94 | 1.67 | 5.2 | <input type="checkbox"/> | 0.0 | 0 | 0.0 | 0.0 | 0.0 |

FIG. 8



BEST AVAILABLE COPY

Replacement Sheet




FIG. 9

Replacement Sheet




FIG. 10

BEST AVAILABLE COPY

Replacement Sheet




FIG. 11

## Replacement Sheet

1200

HEAD

SHAFT

BALL

CLEAR

FIG. 12

Replacement Sheet




FIG. 13

Replacement Sheet




Figure 14